ASSOCIATION RIVER WATER CORS

471 WEST 2ND STREET . OGDEN, UTAH 84404

OFFICERS

JAMES N. RANDALL PRESIDENT

E. A. REED 1ST VICE PRESIDENT

MARK G. HODSON 2ND VICE PRESIDENT

TEREL H. GRIMLEY GENERAL MANAGER

LEE ANN M. FULLER SECRETARY-TREASURER

FREDRICK "BUCK" FROERER III



PHONE (801) 621-6555 FAX (801) 621-6558 INSIDE UTAH - TOLL FREE 1-800-750-6553 RECEIVED

DEC 2 3 1993

WATER RIGHTS

DIRECTORS

JAMES N. RANDALL

LESLIE E. RANDALL

SHERMAN V. WALKER E. A. REED

EDWARD E. KAMMEYER

MARK G. HODSON

ROCKY J. FLUHART

JIMMIE PAPAGEORGE

VERN D. HANCOCK

December 21, 1993

Robert L. Morgan P.E. State Engineer 1636 West North Temple, Suite 220 Salt Lake City, Utah 84116-3156

Dear Mr. Morgan:

The Ogden River Rights Committee met in their annual meeting on December 20, 1993. An issue was brought to our attention that has been ongoing for several years and needs to be resolved.

Over the past several years irrigators on the North Fork of the Ogden River have had a recurring problem with the Southwick and Montgomery Ditch (Right #309) taking more water than they are entitled to receive. This depletes the supply available for the Liberty Irrigation Company. The Southwick and Montgomery Ditch is uncontrolled so the commissioner cannot regulate it during the summer. Your office has written letters to the owners of the water right asking for compliance and installation of a headgate and measuring device. No action has ever been taken to comply and there has been no follow-up from your office.

We request that your office follow-up on this matter and be prepared to discuss it and tell us the steps to be taken to resolve this matter at the annual meeting with the Water Users of the Ogden River Distribution System.

Sincerely.

Chairman Ogder River Rights Committee

cc: Blaine Johnson - Ogden River Commissioner Norman Montgomery Ralph Hansen Norman Wadsworth